Use Attainability Analysis

for

WBID 1006 Tributary to Perche Creek

Submitted by SES, Inc.

To Missouri Department of Natural Resources Water Protection Program

Date Received: September 10, 2007

Field Data Sheets for Recreation Use Stream Surveys Data Sheet A - Water Body Identification

(For water body being surveyed)

Water Body Information

Water Body Name: tributary to perche creek	WBID: 1006
3 digit HUC code: 10300102	County: boone
Jpstream Legal Description 47N13W5	
Downstream Legal Description 47N13W7	
Number of Sites Evaluated 3	
List all site numbers, listed upstream to downstream	
1 2 3	
Discharger Facility Information Discharger Facility Name(s): BCSD, springpark Discharger Permit Number(s):	subd.
MO 0100463	
UAA Surveyor	T. I
Name of Surveyor: Gilisa Gould	Telephone Number: 913-307-0046
Organization/Employer: SES, Inc.	
Position: Field Team Leader	

_D ate:_____

Signed:_____



Field Data Sheets for Recreational Use Stream Surveys Data Sheet B - Site Characterization (must be completed for each site)

WBID 1006 Site # 1

Date and Time: 1:45 PM 5.18.07

Current Weather Conditions clear

Weather Conditions for Past 10 days: partly cloudy

Drought Conditions? No

Site Location (e.g. road crossing) sabine road crossing

GPS Mark: 48

Upstream Photo 105 Downstream Photo 104

Uses Observed (Uses actually observed at time of survey) Circle

Swimming Skin Diving SCUBA diving Tubing

Water Skiing Wind Surfing Kayaking Boating

Wading Rafting Hunting Trapping

Fishing None of the Above Other

Surrounding Conditions

City/county parks Playgrounds MDC conservation lands Urban areas

Campgrounds Boating accesses State parks National Forests

Nature trails Stairs/walkway No trespass sign Fence

Steep slopes None of the Above Other

Indications of Human Use

Roads Rope swings Foot paths/prints Dock/platform

Livestock Watering RV/ATV Tracks Camping Sites Fire pit/ring

NPDES Discharge Fishing Tackle Other:

WBID # Mark #	1006 48		Site # Dissolved	1 Oxygen (p		9.7		
Upstream	Views Phy	sical Dime	nsions:	Is there a	ny water p	resent at this	view?	yes
				If so, is the	ere an obv	rious current?		no
Select one		lowing cha	nnel featur	es:				
Riffle	70 OI OIIGII	inor i cataro						
Run								
Pool						<u> </u>	<u> </u>	
Downstrea	am View's	Physical D	imensions:	Is there an	y water p	resent at this	view?	
				If so, is the	ere an obv	vious current?		
				,				
								_
					1	1	<u>l</u>	
Substrate:								
% Cobble		% Gravel		% Sand		% Silt		
% Mud/Cla	V	% Bedrock	•	7				
70 Widd/Old	<u>y</u>	70 Dedroci	<u> </u>	_				
Aquatic Ve	egetation:	(Note amo	unt of vege	tation or al	gal grow	th at the ass	essment si	te)
				none				
Water Cha	racteristic	s						
Odor		Sewage	Musky	Chemical	None	Other		
Color		Clear	Green	Gray	Milky	Other		
Bottom De	posit	Sludge	Solids	Fine Sed.	None	Other		
Surface De	posit	Oil	Scum	Foam	None	Other		

Data Sheet C: Cross-Sectional Depth Measurements (for estimation of median depth) (Median Depth Shown in Bold)

Site # 1 Mark # 48 1006_Tributary to Perchee creek_Boone

_	Depth (m)		Depth (m)		Depth (m)
Transect 1	0.00	Transect 5	0.00	Transect 9	0.00
Substrate:	0.00	Substrate:	0.05	Substrate:	0.05
cobble	0.05	cobble	0.00	cobble	0.00
Water Clarity:	0.05	Water Clarity:	0.05	Water Clarity:	0.00
clear	0.00	clear	0.00	clear	0.05
Channel Feature:	0.00	Channel Feature:	0.00	Channel Feature:	0.00
riffle	0.00	riffle	0.00	riffle	0.00
Channel Width:	0.00	Channel Width:	0.00	Channel Width:	0.00
5.00	0.00	5.00	0.00	6.00	0.05
0.00	0.00	0.00	0.00	0.00	0.00
Transect 2	0.00	Transect 6	0.00	Transect 10	0.00
Substrate:	0.00	Substrate:	0.05	Substrate:	0.00
cobble	0.00	cobble	0.05	cobble	0.05
Water Clarity:	0.00	Water Clarity:	0.05	Water Clarity:	0.00
clear	0.00	clear	0.05	clear	0.05
Channel Feature:	0.00	Channel Feature:	0.05	Channel Feature:	0.00
riffle	0.00	riffle	0.00	riffle	0.05
Channel Width:	0.00	Channel Width:	0.00	Channel Width:	0.00
5.00	0.00	5.00	0.00	6.00	0.00
0.00	0.00	0.03	0.00	0.00	0.00
Transect 3	0.00	Transect 7	0.00	Transect 11	0.00
Substrate:	0.05	Substrate:	0.00	Substrate:	0.00
cobble	0.05	cobble	0.05	cobble	0.05
Water Clarity:	0.00	Water Clarity:	0.05	Water Clarity:	0.05
clear	0.05	clear	0.05	clear	0.00
Channel Feature:	0.00	Channel Feature:	0.05	Channel Feature:	0.05
riffle	0.00	riffle	0.05	riffle	0.05
Channel Width:	0.00	Channel Width:	0.05	Channel Width:	0.00
5.00	0.00	5.00	0.05	4.00	0.05
0.00	0.00	0.05	0.00	0.03	0.00
Transect 4	0.00	Transect 8	0.00		
Substrate:	0.00	Substrate:	0.00		
cobble	0.00	cobble	0.00	Site Median	Site Maximum
Water Clarity:	0.00	Water Clarity:	0.00	0.00	0.05
clear	0.05	clear	0.05		
Channel Feature:	0.00	Channel Feature:	0.00		
riffle	0.00	riffle	0.05		
Channel Width:	0.00	Channel Width:	0.05		
5.00	0.00	6.00	0.00		
0.00	0.00	0.00	0.00		

Field Data Sheets for Recreational Use Stream Surveys Data Sheet B - Site Characterization (must be completed for each site)

WBID 1006 Site # 2

Date and Time: 3:45 PM 5.18.07

Current Weather Conditions clear

Weather Conditions for Past 10 days: cloudy

Drought Conditions? No

Site Location (e.g. road crossing) downstream of sabine road crossing; middle

GPS Mark: 49

Upstream Photo 107 Downstream Photo 106

Uses Observed (Uses actually observed at time of survey) Circle

Swimming Skin Diving SCUBA diving Tubing

Water Skiing Wind Surfing Kayaking Boating

Wading Rafting Hunting Trapping

Fishing None of the Above Other

Surrounding Conditions

City/county parks Playgrounds MDC conservation lands Urban areas

Campgrounds Boating accesses State parks National Forests

Nature trails Stairs/walkway No trespass sign Fence

Steep slopes None of the Above Other

Indications of Human Use

Roads Rope swings Foot paths/prints Dock/platform

Livestock Watering RV/ATV Tracks Camping Sites Fire pit/ring

NPDES Discharge Fishing Tackle Other:

WBID # Mark #	1006 49		2 d Oxygen (p	pm)	10.5		
Upstream Vie	ws Physica	l Dimensions:	Is there a	ny water p	resent at this	view?	yes
			If so, is the	ere an obv	vious current?		no
	the followin	ng channel featur	es:				
Riffle	or orialinor.	- Cataro					
Run							_
Pool							_
Downstream	View's Phys	sical Dimensions	: Is there an	y water p	resent at this	view?	
			If so is the	ere an obv	vious current?		
			11 00, 10 1110	710 di 1 00 v	nous surrone.		
							1
							_
Substrate:							
% Cobble	% G	Gravel	% Sand		% Silt		1
	lo/ 5		'		•		_
% Mud/Clay	% B	Bedrock					
Aquatic Vege	tation: (Not	e amount of vege	etation or al	gal grow	th at the asse	essment si	te)
			none				
Water Charac	teristics						
Odor	Sev	vage Musky	Chemical	None	Other		
Color	Clea	ar <i>Green</i>	Gray	Milky	Other		
Bottom Depos	it Slu	dge Solids	Fine Sed.	None	Other		
Surface Depos	sit Oil	Scum	Foam	None	Other		

Data Sheet C: Cross-Sectional Depth Measurements (for estimation of median depth) (Median Depth Shown in Bold)

Site # 2 Mark # 49 1006_Tributary to Perchee creek_Boone

	Depth (m)		Depth (m)		Depth (m)
Transect 1	0.00	Transect 5	0.05	Transect 9	0.00
Substrate:	0.00	Substrate:	0.10	Substrate:	0.05
gravel	0.05	silt	0.25	gravel	0.05
Water Clarity:	0.10	Water Clarity:	0.40	Water Clarity:	0.05
clear	0.15	none	0.60	clear	0.05
Channel Feature:	0.10	Channel Feature:	0.70	Channel Feature:	0.05
riffle	0.05	pool	0.90	riffle	0.10
Channel Width:	0.00	Channel Width:	0.60	Channel Width:	0.10
1.00	0.00	5.00	0.40	3.00	0.10
0.03	0.00	0.40	0.10	0.05	0.10
Transect 2	0.00	Transect 6	0.00	Transect 10	0.05
Substrate:	0.00	Substrate:	0.10	Substrate:	0.10
silt	0.10	gravel	0.10	silt	0.15
Water Clarity:	0.10	Water Clarity:	0.10	Water Clarity:	0.20
none	0.10	none	0.10	none	0.20
Channel Feature:	0.20	Channel Feature:	0.10	Channel Feature:	0.20
pool	0.20	pool	0.10	pool	0.20
Channel Width:	0.20	Channel Width:	0.05	Channel Width:	0.15
3.00	0.20	5.00	0.05	3.00	0.10
0.10	0.10	0.10	0.05	0.15	0.05
Transect 3	0.00	Transect 7	0.00	Transect 11	0.00
Substrate:	0.05	Substrate:	0.00	Substrate:	0.05
gravel	0.20	gravel	0.05	silt	0.05
Water Clarity:	0.25	Water Clarity:	0.00	Water Clarity:	0.00
none	0.30	none	0.00	none	0.00
Channel Feature:	0.40	Channel Feature:	0.00	Channel Feature:	0.00
pool	0.40	riffle	0.00	pool	0.05
Channel Width:	0.40	Channel Width:	0.00	Channel Width:	0.10
5.00	0.40	5.00	0.00	5.00	0.10
0.30	0.30	0.00	0.00	0.05	0.05
Transect 4	0.00	Transect 8	0.05		
Substrate:	0.05	Substrate:	0.00		
gravel and silt	0.05	gravel	0.00	Site Median	Site Maximum
Water Clarity:	0.10	Water Clarity:	0.00	0.08	0.90
none	0.10	none	0.05		
Channel Feature:	0.15	Channel Feature:	0.05		
riffle	0.15	riffle	0.05		
Channel Width:	0.10	Channel Width:	0.00		
4.00	0.10	2.00	0.00		
0.10	0.10	0.00	0.00		

Field Data Sheets for Recreational Use Stream Surveys Data Sheet B - Site Characterization (must be completed for each site)

WBID 1006 Site # 3

Date and Time: 5.25.07 1:00 PM

Current Weather Conditions cloudy, with some rain

Weather Conditions for Past 10 days: rain

Drought Conditions? No

Site Location (e.g. road crossing) katy trail access

GPS Mark: 20

Upstream Photo 54 Downstream Photo 55

Uses Observed (Uses actually observed at time of survey) Circle

Swimming Skin Diving SCUBA diving Tubing

Water Skiing Wind Surfing Kayaking Boating

Wading Rafting Hunting Trapping

Fishing None of the Above Other

Surrounding Conditions

City/county parks Playgrounds MDC conservation lands Urban areas

Campgrounds Boating accesses State parks National Forests

Nature trails Stairs/walkway No trespass sign Fence

Steep slopes None of the Above Other

Indications of Human Use

Roads Rope swings Foot paths/prints Dock/platform

Livestock Watering RV/ATV Tracks Camping Sites Fire pit/ring

NPDES Discharge Fishing Tackle Other:

WBID # 1	006	Site #	3	}			
Mark #	20		d Oxygen (p				
Upstream Views	Physical Dime	ensions:	Is there a	ny water	present at this	view?	yes
			If so, is the	ere an ob	vious current?		no
Select one of the	following cha	nnel featu	res:				
	hannel Feature						
Riffle							
Run							
Pool							
Downstream View	w's Physical D	imensions	s: Is there ar	ny water p	oresent at this	view?	
			If so, is the	ere an ob	vious current?		
				T	1	1	_
-				+			\dashv
							_
				1		<u> </u>	
Substrate:							
% Cobble	% Gravel		% Sand		% Silt		
Fax	1		_				
% Mud/Clay	% Bedroc	k					
Aquatic Vegetation	on: (Noto amo	unt of you	otation or a	laal arov	uth at the assu	ocemont (eito)
Aqualic vegetation	on. (Note amo	unt or veg	etation or a	igai grov	viii at tile assi	essment	site)
Water Characteri	stics						
Odor	Sewage	Musky	Chemical	None	Other		
Color	Clear	Green	Gray	Milky	Other		
Bottom Deposit	Sludge	Solids	Fine Sed.	None	Other		

not base flow, flooded

Data Sheet C: Cross-Sectional Depth Measurements (for estimation of median depth) (Median Depth Shown in Bold)

Site #3 Mark # 20 not base flow

		a.r.		1006_Tributary to Per	chee creek Boone	
	Depth (m)		Depth (m)	Depth (m)		
Transect 1	0.10	Transect 5	0.05	Transect 9	0.10	
Substrate:	0.15	Substrate:	0.05	Substrate:	0.15	
clay	0.15	silty clay	0.05	silty clay	0.15	
Water Clarity:	0.15	Water Clarity:	0.05	Water Clarity:	0.10	
some	0.25	clear	0.05	clear	0.10	
Channel Feature:	0.25	Channel Feature:	0.00	Channel Feature:	0.20	
pool	0.25	pool	0.00	pool	0.20	
Channel Width:	0.20	Channel Width:	0.00	Channel Width:	0.20	
3 yards	0.20	5 yards	0.00	5 yards	0.20	
0.18	0.10	0.03	0.00	0.15	0.10	
Transect 2	0.05	Transect 6	0.00	Transect 10	0.50	
Substrate:	0.10	Substrate:	0.00	Substrate:	0.10	
clay	0.10	silty clay	0.05	silty clay	0.10	
Water Clarity:	0.05	Water Clarity:	0.00	Water Clarity:	0.10	
clear	0.10	clear	0.00	clear	0.10	
Channel Feature:	0.10	Channel Feature:	0.00	Channel Feature:	0.05	
pool	0.05	pool	0.00	pool	0.00	
Channel Width:	0.05	Channel Width:	0.00	Channel Width:	0.00	
2 yards	0.10	4 yards	0.00	4 yards	0.00	
0.08	0.05	0.00	0.00	0.08	0.00	
Transect 3	0.05	Transect 7	0.00	Transect 11	0.05	
Substrate:	0.10	Substrate:	0.00	Substrate:	0.10	
silty clay	0.10	silty clay	0.00	silty clay	0.10	
Water Clarity:	0.10	Water Clarity:	0.05	Water Clarity:	0.10	
clear	0.15	clear	0.00	clear	0.05	
Channel Feature:	0.20	Channel Feature:	0.00	Channel Feature:	0.00	
pool	0.20	pool	0.00	pool	0.00	
Channel Width:	0.15	Channel Width:	0.00	Channel Width:	0.00	
6 yards	0.15	4 yards	0.00	4 yards		
0.13	0.10	0.00	0.00	0.03	0.00	
Transect 4	0.50	Transect 8	0.00			
Substrate:	0.50	Substrate:	0.10			
silty clay	0.10	silty clay	0.10	Site Median	Site Maximum	
Water Clarity:	0.10	Water Clarity:	0.05	0.05	0.50	
clear	0.10	clear	0.05			
Channel Feature:	0.05	Channel Feature:	0.10			
pool	0.05	pool	0.05			
Channel Width:	0.05	Channel Width:	0.05			
2 yards	0.50	5 yards	0.05			
A 4A	0.00	^ ^=	0.05			

0.05

0.05

0.00

WBID# 1006



Site# 1 Photo ID# 105, Upstream



Site# 2 Photo ID# 107, Upstream



Site# 1 Photo ID# 104, Downstream



Site# 2 Photo ID# 106, Downstream

WBID# 1006



Site# 3 Photo ID# 54, Upstream



Site# 3 Photo ID# 55, Downstream